Nikon

Windows XP Home Edition / Windows XP Professional

Nikon Scan (Ver.3.1.2)

This manual is for those users who are running Nikon Scan (Ver. 3.1.2) under Windows XP Home Edition / Professional.

Registering a Scanner with Windows XP

(SUPER COOLSCAN 8000 ED / SUPER COOLSCAN 4000 ED /COOLSCAN IV ED / LS-2000 / COOLSCAN III)

The screenshots in this manual show the registration procedure for the SUPERCOOLSCAN 4000ED. The camera must be registered as a hardware device when it is connected to the computer for the first time.
You will need to log on as the "Computer Administrator" when registering a scanner. Note that you should also log on as the "Computer Administrator" when using, installing or uninstalling Nikon Scan.

Step 1

The first time the scanner is connected to the computer, the "Found New Hardware Wizard" will be displayed. Select **Install from a list or specific location** and click **Next**.


Caution (LS-2000 / COOLSCAN III Users)
You will need the Windows XP compatible ASPI layer for your SCSI board or SCSI card in order to use the LS-2000 and the COOLSCAN III with Windows XP.

Step 2

The dialog shown below will be displayed. Select **Search for the best driver in these locations,** then check **Include this location in the search**.

If, for example, the *Inf* Folder created when you ran the downloaded *nsinfxp.exe* file is inside "New Folder", click the **Browse** button, and select "C:\New Folder\Inf".


Click **OK**; the dialog shown below will be displayed.

As an example, the above screenshot shows the driver location as "C:\New Folder\Inf".

Step 3

During the driver installation, the dialog shown at right will appear; click **Continue Anyway**, and carry on with the installation.


Step 4

When the driver installation has been completed, the dialog shown below will be displayed; click **Finish** to close the wizard.

Step 5

Once registration is complete, follow the steps below to check that the scanner has been correctly registered with the system.

Select **Control Panel** from the **Start** menu to display the window shown below. Click **Performance and Maintenance**.


Step 6

The Performance and Maintenance window will be displayed. Click **System.**


Step 7

The System Properties window will be displayed. Select the Hardware tab and click the **Device Manager** button in the Device Manager section.

Step 8

The Device Manager window will appear. Confirming that "Imaging Device" is listed in the Device Manager window, and click the "+" next to the listing.

Step 9

After confirming that "(the name of your scanner)" is listed under "Imaging Device," double-click the listing to open the Properties window.

Step 10

The Properties dialog for your scanner will be displayed. Click the General tab and confirm that "This device is working properly" appears under "Device status". Click **OK**.

Close the Device Manager, then click **OK** to close the System Properties window. Device registration is now complete